

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 7



	PI	VI	HI	UI
Unit	x		x	x
Sub Unit	x		x	x
Loop		x	x	x
Device		x	x	

FIG. 9

PERFORMANCE FOR FCCU: 83.2



575 {

Loop Name	Index	Weight
FIC-101	88	3
TIC-111	89	3
LIC-111	88	3
FIC-111	60	3
FIC-112	80	1
TCI-222	87	1
FIC-101	88	3
TIC-111	89	3
LIC-111	88	3
FIC-111	60	3
FIC-112	80	1
TIC-222	87	1
PIC-111	87	1

FIG. 10

FCCU Health: 97.5

Device Name	Index	Description	Weight
FV-111	100	Leaking	3
TI-111	98	Sticktion	3
<u>LI-111</u>	90	40	3
MC-101	95	Will burn up in 2 weeks	3
FV-111	96	0	1

FIG. 11

FCCU Variability: 12.1

Device Name	Index	Weight
FV-101	0	3
TI-111	2	3
LI-111	40	3
FV-111	0	3
FV-112	0	1
TI-222	2	1
FI-101	7	3
TI-111	6	3
LI-111	7	3
FI-111	7	3
FI-112	7	1
TI-222	7	1
Sub unit: Reboiler RB101	15	2

FIG. 12

Alarms

Process

Impulse Line

Plugged Impulse Line Detection

Time Stamp

12:72:12

Status

☐ OK

☐ Inactive

☐ Learning

☐ Verifying

☒ Insufficient Dynamics

☐ Bad PV Status

☐ Not Licensed

☐ All Lines Plugged

Plugged Impulse Line History

Time Stamp

16:72:12

Status

☒ All Lines Plugged

☐ No History

FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19





FIG. 20






FIG. 22





FIG. 23

FIG. 24






FIG. 25




FIG. 26

Work Order		Plans	Actuals	Costs	WO Hierarchy	Safety Plan	Failure Reporting	Linked Documents
<div> <div> <div>Work Order</div> <div>1194</div> </div> <div> <div>Location</div> <div>BDCUBE</div> </div> <div> <div>Equipment</div> <div>TI-111</div> </div> <div> <div>Reported By</div> <div>MAXIMO</div> </div> <div> <div>Status</div> <div>WSCH</div> </div> <div> <div>GL Account</div> <div></div> </div> </div> <div> <div>SENSOR MEASUREMENT</div> <div>AMS Business Development Cubicle</div> <div>Rosemont 3044C in BD Cube</div> <div>Reported By</div> <div>8/18/00 1</div> <div>Work Phone</div> <div></div> <div>Charge to Store?</div> <div>N</div> </div> <div> <div>WO Priority</div> <div>5</div> <div>Loc/Eq Priority</div> <div></div> <div>Equipment Up?</div> <div>Y</div> <div>Warranty Date</div> <div></div> <div>Work Type</div> <div>EM</div> </div>								

Job Details

Problem

Follow-up Work

Job Plan

Safety Plan

PM

AMS10130

Service Contract

Failure Class

Problem Code

Originating WO

Has Follow-up Work?

N

Scheduling Information

Responsibility

Start

Target

8/18/00 11:42AM

Scheduled

Actual

Completion

8/18/00 11:42AM

Supervisor

Labor Group

Lead Craft/Person

Modified

Crew

Interruptible?

Estimated Duration

0.00

Remaining Duration

By

Maximo

Date

8/18/00 1

FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33